#### UNCLASSIFIED

# AD NUMBER AD505600 CLASSIFICATION CHANGES TO: UNCLASSIFIED FROM: CONFIDENTIAL LIMITATION CHANGES

#### TO:

Approved for public release; distribution is unlimited.

#### FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors;
Administrative/Operational Use; 01 AUG 1969.
Other requests shall be referred to Assistant Chief of Staff for Force Development (Army), Washington, DC 20310.

#### **AUTHORITY**

AGO D/A ltr dtd 29 Apr 1980; AGO D/A ltr dtd 29 Apr 1980

THIS REPORT HAS BEEN DELIMITED

AND CLEARED FOR PUBLIC RELEASE

UNDER DOD DIRECTIVE 5200,20 AND

NO RESTRICTIONS ARE IMPOSED UPON

ITS USE AND DISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED.

### SECURITY MARKING


The classified or limited status of this report applies to each page, unless otherwise marked.

Separate page printouts MUST be marked accordingly.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U.S. Government thereby incurs no responsibility, nor ny obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

# DISCLAIMER NOTICE



THIS DOCUMENT IS BEST QUALITY AVAILABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.



#### DEPARTMENT OF THE ARMY OFFICE OF THE ADJUTANT GENERAL

WASHINGTON, D.C. 20310

AGDA (M) (28 Oct 69)

FOR OT UT 693138

5 November 1969

SUBJECT: Operational Report - Lessons Learned, Headquarters, 269th Aviation

Battalion, Period Ending 31 July 1969 (U)

SEE DISTRIBUTION Defer

This document was

Ispio.:

794.

in any L.

. . . the National . Z of the

> ) and · cantents

, . . inited /

1. Subject reporty is forwarded for review and evaluation in accordance with paragraph 5b, AR 525-15. Evaluations and corrective actions should be reported to ACSFOR OT UT, Operational Reports Branch, within 90 days of receipt of covering letter.

2. Information contained in this report is provided to insure appropriate benefits in the future from lessons learned during current operations and may be adapted for use in developing training material.

BY ORDER OF THE SECRETARY OF THE ARMY:

KENNETH G. WICKHAM Major General, USA The Adjutant General

1 Incl

DISTRIBUTION:

Commanding Generals

US Continental Army Command

US Army Combat Developments Command

Commandants

US Army War College

US Army Command and General Staff College

US Army Armor School

US Army Aviation School

US Army Combat Surveillanca School

US Army Electronic Warfare School

US Army Engineer School

US Army Field Artillery School

US Army Infantry School

US Army Missile and Munitions School

US Army Ordnance School

Regraded unclassified when separated from classified inclosure.

DISTRIBUTION (Cont'd)

269th Aviation Battalion

US Army Quartermaster School US Army Signal School US Army Southeastern Signal School US Army Special Warfare School US Army Transportation School Copies furnished: Office, Chief of Staff, US Army Deputy Chiefs of Staff Chief of Research and Development Assistant Chiefs of Staff Chief of Engineers OSD(SA) Assistant for Southeast Asia Forces Director, Defense Research and Engineering Office, Joint Chiefs of Staff Commanding Generals US Army Materiel Command US Army Electronics Command US Army Weapons Command US Army Flight Training Center Deputy Chief of Staff, Air Force, Plans & Operations Commandant of the Marine Corps Senior Army Representative, Marine Corps Development & Education Command The Air University Library Defense Documentation Center Security Officer, Hudson Institute USAF Project RAND Commanding Officers US Army Limited War Laboratory US Army Logistics, Doctrine Systems & Readiness Agency US Army Aviation Test Activity US Army Mobility Equipment Research & Development Center

#### DEPARIMENT OF THE ARMY HEADQUARTERS 269TH AVIATION EXTTALION (COMPAT) APO 96353 "DISCIPLINED PROFESSIONALS"

AVBACA\_F\_SC

1 August 1939

SUBJECT: Operational Report-Lessons Learned for the Period Ending 31 July 1969 (UIC: WEUTTO) (NCS CSFOR - 65) (RI)

SEE DISTRIBUTION

- 1. Peferences AR 525-15 and USARV Regulation 525-15.
- 2. Attached is the Operational Report-Lessons Learned covering the activities of the 269th Aviation Battalion (Combat) for the period 1 May 1969 through 31 July 1969.

FOR THE COMMANDER:

1 Incl ೭ಽ

(or DENNIS A. RALFIGHT, Got, aut adj. 1LT, OR Asst: Adjutant

Distribution: CINCUSARPAC, ATTN: GPOP-DT, APO 96558 (2 Cys)

GG, USARV, ATTN: AVHCG-DST, APO 96375 (3 Cys)

GG, 1st Avm Bde, ATTN: AVBAGC-O, APO 96384 (2 Cys)

GG, 25th Inf Div, ATTN: ACofs, G3, APO 96225 (1 Cy)

GO, 12th Avm Gp (Cbt), ATTN: AVBAGA-SC, APO 96266 (5 Cys)

CO, 11th Avm Bn (Cbt), APO 96259

GO, 145th Avm Bn (Cbt), APO 96277

GO, 210th Avm Bn (Cbt), APO 96307

GO, 214th Avm En (Cbt), APO 96370

CO, 222nd Avm En (Cbt), APO 96291

GO, 3rd Scdn, 17th Cav, APO 96289

CO, 25th Avm Dn, APO 96225

GO, 116th Avm Co (Aslt Hel), APO 96353 CHICUSARPAC, ATTN: GPOP-DT, APO 96558 (2 Cys)

CO, 116th Avn Co (Aslt Hel), APO 96353 00, 187th Avn Co (Aslt Hel), APO 96216 00, 242nd Avn Co (Aslt Spt Hel), APO 96353

Regraded unclassified when separated from ciassified inciosure.

## DEPARTMENT OF THE ARMY FRADQUARTERS 269TH AVIATION BATTALICY (COMBAT) APO 95353 "DISCIPLINED PROFESSIONALS"

AVEACA\_F-SC

1 August 1969

SUBJECT: Operational Report-Lessons Learned of the 269th Aviation Battalion (Combat) for the Period 1 May 1969 through 31 July 1969 (U)

SEE DISTRIBUTION

#### I. (C) Section 1. Operations: Significant Activities.

- a. <u>Mission</u>: During this reporting period there has been no change in the 269th Aviation Battalion (Combat) mission.
- b. Organization: During this reporting period there has been no change in the organization of the 269th Aviation Battalion (Combat). Present organization attached as Liclosure 1.

#### c. Personalities:

- (1) Commander: The Commanding Officer of the 269th Aviation Battalion (Combat) is LIEUTENANT COLONEL WILLIAM A. LAWRENCE, 546-38-1843, Field Artillery, who replaced LTC GEORGE W. MC ILWAIN on 13 June 1969.
- (2) Staff: The principal staff officers during the reporting period were:
- (a) Executive Officer: MAJOR RICHARD J. HUSTON, 279-26-8229, Armor, who replaced MAJOR GARY L. KEEFER, on 13 July 1969.
- (b) S-1: 1ST LIEUTENANT FRANCIS R. BASKIND, 122-34-4210; Adjutena General Corp., no change.
  - (c) S-2: 1ST LIEUTENANT THOMAS G. GARDNER, 237-72-3407, Infantry

no change.

FOR OTUT 693138 Inclosure CONFIDENTIAL

DOWNGRADED AT 3 YEAR INTERVALS; DECLASSIFIED AFTER 12 YEARS. DOD DIR 5200.10

- (d) S-3: MAJOR GERALD R. KUNDE, 394-34-6505, Infantry, who replaced MAJOR RICHARD J. HUSTON, on 22 July 1969.
- (e) S-4: CAPTAIN JOHN W. DAVIS JR, 414-78-4171, Transportation Corp, who replaced CAPTAIN GEORGE D. CRITTENDEN, on 23 July 1969.
  - (3) Subordinate Unit Commanders:
- (a) Headquarters Company: CAPTAIN FORMED M. DAVIS, 004-42-9980, Infantry, who replaced CAPTAIN BALLARD M. BARKER, on 5 July 1969.
- (b) 116th Aviation Company (Assault Helicopter): MAJOR ALVIN T. JOHES 175-30-0056, Infantry, who replaced MAJOR JAMES F. SOSSAMON, on 13 July 1969.
- (c) 187th Aviation Company (Assault Helicopter): MAJOR JERRY R. STRATTON, 522-40-6923, Infantry, no change.
- (d) 242nd Aviation Company (Asseult Support Holicopter): MaJOR MAS M. NAKAJO, 561-54-9711, Field Artillery, no change.

#### 2. (C) <u>S-1</u>

Personnel and Administration:

a. Maintenance of Unit Strongth: The Battalion strongth as of 31 July 1969 is shown as Inclosure 2. The summary of projected losses during the next 90 days is shown in Inclosure 3.

b. Replacements have been requisitioned in accordance with current directives. Although there remains some critical emlisted MOS shortages, the overall replacement progrem has functioned smoothly and efficiently. Following is a surnery of personnel gains and losses during the period 1 May to 31 July 1959.

(1) Assignments:

OFFICERS	WARRANT OFFICERS	MILSTED	
27	25	169	

(2) Rotation to CONUS:

OFFICERS	MARRANT OFFICERS	Filisied
11	21	131

(3) Casualties Returned to Duty:

<u>Officers</u>	WARRANT OFFICERS	EVILL ST'KD
1	1	5

(4) Casualties Evacuated:

OFFI CERS	WARRANT OFFICERS	EVILISIVED
2.	9	12

(5) Killed in Action:

OFFICEIS	WARRANT OFFICERS	EXLISTED	
4	2	5	

- c. Reonlistment: There was a total of five (5) reenlistments in the Battalion during this quarter.
  - d. Promotions. Promotion during this quarter were as follows:

CPT	1LT	CW2	<u>F_8</u>	<u>E-7</u>	<u>R-6</u>	<u>-5</u>	B-4
16	0	21	1	4	5	25	37

- e. Reclassifications: A total of 111 enlisted personnel were administratively reclassified during the quarter. The primary reason for this action was upgrading of MOS skills, adjustments in MOS to jobs performed and enlisted promotions.
- f. Retirements: There were no retirements or reversion to retired status during the quarter.
- g. Civilian Personnol: There has been no change in the civilian personnel program administered by this battalion. Permanent hire personnel levels continue to be allocated by 12th Aviation Group (Combat) IAW USARV Regulation 690-7. There has been a general cut back in the number of daily hire personnel. This reduction has been necessary in light of the reduced funds available.
- h. Awards and Ceromonies: Forty-three (43) awards ceremonies have been held during the quarter. Headquarters Company hold 11 ceromonies, with the Company Commander presenting the awards. One award ceromony was held at the 140th Aviation Company (Assault Helicopter) with the Company Commander presenting the awards. Six (6) awards coremonies were held at the 187th Aviation Company (Assault Helicopter) with the Company Commander presenting the awards. The 242nd Aviation Company (Assault Support Helicopter) held 25 awards ceromonics with the Company Commander presenting the awards.

Distinguished Flying Cross to the Purple Heart were presented. A Change of Cormand Ceremony was conducted on 13 June 1969, LTC WILLIAM L. LLWRENCE assumed command of the 269th Aviation Bettalion (Combat). On 13 June 1969, Major Alvin T. JONES assumed command of the 116th Aviation Company (Assault Helicopter).

On 5 July 1969 CAPTAIN RONALD M. DAVIS assumed command of HHC 269th Aviation Battalion (Combat).

- i. Moralo and Personal Services The overall morale of the battalien personal remains at an excellent level. Contributing factors toward the maintonance of this morale have been increased attention to personal services, an active program and an enlivened spirit of competition within and between subordinate units.
- (1) The R2R progrem is continually stressed throughout the battalion.

  During the quarter the battalion received and filled 227 quotas.
  - (2) Leaves granted during the quarter were as follows:

	<u>OFFICERS</u>	WARRANT OFFICERS	FILISTED
EMERGENCY	1	3	7
CONTASSIONATE	0	0	O
SPECIAL	2	1	26
ORDINARY	10	4	6

- (3) Postel Sorvice: Postal sorvices have continued to be excollent thereby greatly assisting the morale of battalion personnel.
- j. Discipline, Law and Order: During the past quarter the following disciplinary actions have been conducted:
  - (1) Special Court Martial 9
  - (2) Summery Court Mertial 1

- (3) Genoval Court Martial 0
- (4) Article 15 Impositions 48
- (5) 4 Cases of Confinement have been suspended.
- k. Marriago to Foreign Nationals: None
- 1. Exchange Facilities, Clubs and Messes: There has been no change in these facilities during the quarter.
  - m. Information Activities:
- (1) No major changes have been made in the command information program of this battalion, although new ideas and concepts have been incorporated into the existing information program.
- (2) Command emphasis at all levels has increased participation and resulted in more personal interest stories, stressing on individuals achievements and job performed by the personnel. The number of hometown news releases have been increasing, and the primary objective being stressed is the achievements in all areas of eviation and combat operations.

#### 3. (U) <u>8-2</u>

Intelligence and Security:

- a. The intelligence section continues its primary mission of gathering and disseminating timely and accurate intelligence from all reliable sources for use by the staff and the companies to assist in the accomplishment of their assigned mission.
- b. It was noted in correspondence received by the intelligence section during the reporting period that a more vigorous program was needed to insure that all personnel assigned to this command were aware of astablished procedures for the disposal of personal correspondence, the reporting procedures for SAEDA violations, and the necessary steps to be initiated when an individual receives any unsolicited correspondence. To insure that all individuals within this command are aware of this information, it is now required by this headquarters that all companies, in addition to the required in-country security briefing, give a class monthly on this information.
- c. All frequently used facilities within the command continue to be inspected on a daily basis for possible acts of sabotage. Reports are due from the companies to the S-2 office the date following the date of the inspection.

  The company reports are consolidated into a monthly report by the Battalian S-2, reviewed by the Battalian Commander and filed in the S-2 section.
- d. Bocause of the ready availability of secret documents to the compenies on Cu Chi Base Comp from the Battalion Repository, companies stationed at the same installation as Battalion Headquarters will no longer maintain a Secret Document Register. Secret documents needed by the companies will be receipted on a DA Form 1203 on a short period basis. Companies not stationed at the same

facility as Battelian Headquarters will continue to maintain a Secret Document Register.

e. The 269th Aviation Battelion (Combat) continues the mission of commanding Sector "E" of the Cu Chi Base Comp defensive perimeter.

#### 4. (U) <u>S-3</u>

Operations and Training:

- a. Operations: The frequency of combat assaults performed by the battalion has remained at the same high level as the pest quarter. The battalion continues to be committed daily to tasks varying from combat support missions to battalion sized combat assault operations, with emphasis being placed on company sized combat assault operations. The battalion flew a total of 178 combat assault days of the possible 184 days. For more statistical data see Inclosure 5. The battalion is normally committed daily for two combat assault companies, two general support aircraft (UH-1D/H) and six (6) CH-474 aircraft for general support from the 242nd Aviation Company (Assault Support Helicopter). The normal mission profile for the assault helicopter company is nine (9) UH-1D/H lift helicopters, one command and control helicopter and four armed helicopters from the units assets.
- (1) The 116th and the 187th Aviation Companies (Assault Helicopter) continue as the primary non-divisional aviation support for the 25th Infantry Division. A breakdown of percent of support per flying hour is as follows: JUNE
  - (a) 116th Aviation Company (Assoult Helicopter):
    - 1 48% 25th Infantry Division
    - 2 38% CMAC
    - 3 12% 9th Infentry Division
    - 4 2% Navy
  - (b) 187th Aviation Company (Assault Helicopter):
    - 1 93% 25th Infantry Division
    - 2 3% 1st Infantry Division

#### JULY

- (a) 116th Aviation Company (Asseult Helicenter):
  - 1 54% 25th Infantry Division
  - 2 29% CMAC and 9th Infantry Division
  - 3 5% Other
- (b) 187th Aviation Company (Assault Helicopter):
  - 1 97% 25th Infantry Division
  - 2 3% 5th Special Forces Group
- (2) The 242nd Aviction Company (Asscult Support Helicopter) maintained its high level of support for all allied forces in the III Corps Tactical Zene. The 242nd Avn Co is normally committed each day for three (3) aircraft in support of the 25th Infentry Division and three (3) aircraft in support of II Field Forces. With the use of our organic Fathfinder Detachment, the 242nd has expedited the movement of artillery batteries and large scale troop movements. The pathfinders being more experienced in aviction operations, can assist the ground commander in rigging heavy loads, positioning troops in the IZ and actual radio control of aircraft in the PZ's and LZ's.
- (3) This bettelion attempts to maintain the habitual association down to company level by assigned missions to specific brigades within the division. The 116th Aviation Company (Assault Helicopter) located at Cu Chi provides the privary air assets for the 2nd Brigade located at Cu Chi. The 187th Aviation Company (Assault Helicopter) located at Tay Ninh provides the privary air assets in the 1st Brigade located at Tay Ninh provides the privary air assets in the 1st Brigade located at Tay Ninh. Poth companies work for 3rd Sciende to deal at the total at Brigade located at Tay Ninh.

- (4) The najority of the combat assaults conducted by the battalion are controlled by the individual companies. The 25th Infantry Division seldom initiates assaults of multi-company size. During the past quarter two (2) battalion lifts were conducted and controlled by the battalion. Coordination of effort of all assigned units is maintained through the battalion operations center. By maintaining a close menitoring of mission progress and unit status, BOC Duty Officers can readily shift assets within the battalion to neet unforscen requirements.
- (5) During the last reporting period the 187th Avn Co (Aslt Hel) was assigned three (3) AH-1G (Cobras). They have worked into the assault helicopter operations very well. The 187th is still waiting to receive issue of three (3) nore AH-1Gs to make its gun plateon complete with six (6) AH-1Gs.

#### b. Training:

(1) During the reporting period the 269th Aviation Battalion (Combat) sent 149 individuals to the Viotnam In-Country Training Program conducted by the 25th Infantry Division located in Cu Chi. The five (5) day course is designed for personnel assigned to one of the field units, but it is also very advantageous to individuals such as clerks, mechanics, and aviation personnel who would not otherwise receive this type of training. This training provides the individual with a basic knowledge of the combat skills he will be expected to know and use during his tour in Vietnam. Some of the subjects covered are enough weapons, enough mine, booby traps, patrolling, land navigation, ambush and counter ambush techniques. The training course also includes instruction in weapons familiarization to include the M-14, M-16, M-60, M-79 grenade launcher and zeroing of individual weapons. This is an outstanding program and the

269th Bettelion will continue to sond members as long as quotas are available.

(2) Army Aviation Refresher Training School (ALTS): The following
LLTS school quotes were received and filled by personnel from units indicated:

COURSE	116th	187th	21.2nd	ннс
AH_1G/UH_1C Airframe	1	2	0	0
CH_47 Airframe	0	0	4	0
T-53-I-13	1	1	0	0
T-55-L-7	0	0	2	0
Tech Supply	1	2	0	0
Enlisted Armament	0	1	0	0
Officer Armanent	1	0	0	0
Tech Inspector	1	1	С	0
CH_47 Maint Supervisor	0	0	7	1

- (3) Aviator Training and Standardization:
- (a) Two (2) ellocations for AH-1G transition were received and filled by the 187th Avn Co (Asl: Hel).
- (b) One (1) allocation for UH-1 Instructor Pilot was received and filled by the 187th Lvn Co (Last Hel).
- (c) Primary training to newly assigned aviators in conducted at subordinate unit level. In-country orientations are given by company level instructor pilots, as are the various stages of training required to insure an aviators proficiency in the techniques peculiar to combat operations in Vietnam.
- (d) Standardization is maintained throughout the battalion through 90 day standardization checkrides. These rides are given by company and batta-

lion instructor pilots who insure adherence to battelion standards. Battalion standardization pilots continually monitor the standardization program with an aggressive policy of frequent flying with the subordinate units.

#### 5. (U) <u>S-A</u>

Logistics:

- a. Recently, some question arose portaining to the accountability of the rockets this headquarters is allocated. Previously, our allocation was received by 25th Infantry Division so that they could account for and order received by 25th Infantry Division so that they could account for and order receives that our gunships would fire during a given time frame. Subsequently, this headquarters had little knowledge concerning the number and type of receives that we were allocated. After this problem came to light, our S-4 coerdinated closely with 12th Aviation Group S-4, 25th Inf Div G-4 and the Division Arms Officer to make us more aware of the rocket situation. Resolution of this question came about by having 12th Aviation Group (Combat) Headquarters send the receive allocations to this C-4 and, in turn, the allocation is hand carried to Division. The 1,6th and 187th Aviation Companies (Assault Helicopter) are notified as to the number and type of rockets they may fore during the given this period, in order that they was are aware of our available rocket assets.
- b. Automotive Maintenance: Through a process of transferring and giving to ded parts from one company in our battalion to another, we have realized a feeline in our rate of deadlined vehicles. This same system is being attempted to a Group-wide scale and preliminary reports show a tendency toward favorable results.
- c. Construction: The 242nd Aviation Company (Assault Support Helicopter) hanger project is presently number 21 in the priority 2 category with no definite starting date evallable. Their revetment area, number 4 in the priority 1 category, is approximately 74% complete with three (3) revetments yet to with Aviation Battalion (Combat) VIP/Transit Billets work orders

are still pending approved by the Installation Engineer's Office.

#### d. Aircraft Maintenences

- (1) Through the combined efforts of the Battalian Maintenance Section, this battalian has maintained its high availability rate. The combined average for this quarter is 83.7 percent, a decrease of 2.1 percent from the last quarter. While the availability percentage shows a docrease, the flying hours have increased. The 116th and 167th Aviation Companies (Assault Helicopter) have flown an average 103.2 hours per aircraft per month during this reporting period, an increase of 7.7 hours per aircraft. The 242nd Aviation Company (Assault Support Helicopter) has flown 74.7 hours per aircraft per month during this reporting period, an increase of 8.1 hours per aircraft.
- (2) The 2/2nd Aviation Company (Assault Support Helicopter) has been presented the 1st Aviation Brigade Safety Plaque for the last quarter fiscal year 1969. This is due to outstanding efforts of the unit maintenance personnel and crows.
- (3) The airmobile shop sets have been issued minus a few components. These items were kept from the old shop sets, and are now in full use at the 116th and 187th Aviation Companies (Assault Helicopter). The airmobile shop sets for the 242nd Aviation Company (Assault Support Helicopter) was issued minus the number 3 set (sheet metal), to preclude a work stoppage because of sheet metal, the old sheet metal van was retained, but will be turned in when the airmobile set number 3 is issued. All unit report that the old sets have been turned in to the 20th Transportation Company at Ou Chi.

(4) The chief problem area in this field has been obtaining parts for CP-474. These parts, combining boxes and rotor blades in particular, have been acquired by transferring parts off retrograded and damaged aircraft to potentially flyable circraft.

#### 6. (U) Signal

a. The secure voice (TSEC/KY-28) program has programed slowly due to a couple of setbacks. It was found that a large number of the ZYS modifications have been incorrectly wired and has to be returned to the LSI team for correction. A trouble spot also was not all the AN/ARC-54 radios had received the module modification required to insure secure vocie adapability. This is a recurring problem since the units constantly receive DX ARC-54's which have not been modified. The last problem area encountered was with the KYK-28 keying gun. The gun will go out of adjustment and not set the proper key for the day. Installation of KYK-28 in the CH-47's are still pending a control head modification which was not as yet been authorized.

phone cabling was postponed pending the completion of the power wiring systems for the new central power plant. New power cables should be up and the old ones down by mid-August. The new 50 pair telephone cable may be strung on the new power poles within the area.

c. FM Antonna-90! Pole. Plans for erection of a 90! telephone pole for the FM antonna complex has been temperarily interrupted. The pole has been obtained and the "top-hat" complex has been constructed. Final approval for its crection from the mirfield commander is still pending.

#### 7. (U) Surgeon

- a. The 269th Aviction Bettalion (Combat) Disponsary is presently working under its new TOSE. The dispensary is on central power and has all of its air conditioners in operation. With its X-ray and audiometer equipment, this dispensary now can do a complete flight physical. Medical personnel are attached to the various 269th Aviation Battalion (Combat) units at Cu Chi base camp for lodging to be available in emergency situations.
- b. The 541st Medical (OL) Detachment supports the 187th Aviation Company (Assault Helicopter) at Tay Ninh. The dispensary was hit by a rocket and burned to the ground on 6 June 1969. A temporary location was set up for the dispensary and it was fully operational within 8 hours.
- c. The battalion proventive disease rate remains low with very few man hours lost to illness. This factor is a tribute to the high standards of sanitation and hygiene maintained in the battalion. This quarter there were 10% orthopodic, 10% skin diseases, 20% URI, and the rest were other medical and surgical problems. There were no reported cases of malaria during this quarter.

#### 3. (U) Safety

- 2. During the month of May, the 269th Aviation Battalion (Combat) increased command emphasis towards the Aviation Safety Program in an effort to derive complete effectiveness. Command emphasis continued on safety, not only by this headquarters but by higher headquarters in an effort to bring about a substantial reduction in aviation accidents with in the 1st Aviation Brigade. The month of July, bearing the full effort of command emphasis on the Safety Program, began to reveal the effects of what can be accomplished when all personnel are made aware of safety. Safety is each individuals job and it is the Commanders responsibility to see that all personnel within the command instill into their environment the policy of good safe habits.
- b. The 269th Aviation Battalion (Combat) "Safety Disc" awarded to the individual plateons of the assault companies for flying the most safe flying hours, was presented to the first plateon of the 116th Aviation Company (Assault Helicopter) for the months of May and July. Headquarters and Headquarters Company was presented the "Safety Disc" for the month of June.
- c. The 242nd Aviation Company (Assault Support Helicopter) was recognized at the safest assault support helicopter company for the fourth quarter in the 1st Aviation Brigade. The Brigade Safety Plaque was presented to the 242nd Aviation Company for this accomplishment. The 242nd Aviation Company had a safety record of eight accident free months, flying 9,192 accident free hours.

#### 9. (U) Chanlain

- a. Religious Services and Character Quidance.
- (1) Religious services for the three major faiths are available to all personnel within the cornand. Denominational Services are also available for various Protestant denominations. Services for Roman Catholic personnel are provided by Chaplains from the 25th Infantry Division. Roman Catholics in the 269th Aviation Battalion (Combat) have a mass in the Battalion Chapel, those in the 242nd Aviation Company (Assault Support Hiscopter) have a Mass in the dayroon, the 116th and 187th Aviation Companies attend mass in the Division Manorial Chapel and Brigade Manorial Chapal respectively, due to the close location of each. Jowish personnel in the units located at On Chi base camp attend services in the 25th Division Manorial Chapel. Special arrangements are made for those at Tay Ninh. All Jowish personnel are provided arrangements to attend days of special obligation such as Passover.

  The Eattalion Chaplain conducts Protestant Worship Services for the units as follows
  - (a) HHC 269th Aviation Battalion (Combat):
    - 1 SUNDAY: 1100 nours Battalion Aim High Chapel.
    - 2 TUESDAY: 1930 hours Battalion Aim High Chapel.
  - (b) 116th Aviation Company (Assault Helicopter):
    - 1 SUNDAY: 1000 Hornet's Pool Arca .
    - 2 MONDAY: 1930 Hours Hornot's Pool Area.
  - (c) 187th Aviation Company (Assault Hiscopter):
    - 1 SUNDAY: 1930 Hours Crusador Moss Hall
  - (d) 2/2nd Aviation Company (Assault Support Helicopter):
    - 1 SUNDAY: 0900 hours Muleskinnor's Day Room
    - 2 THURSDAY: 1930 hours Muleskinner's Day Room.

- 1 SUNDAY: 0900 hours Muleskinner Dayroom.
- 2 THURSDAY: 1930 hours Muloskinner Dayroom.

Attendences at Protestent and Roman Catholic Services is on the increase. Greater caphasis on worship services and additional opportunities for attendance have helped create this.

- b. The Battalier Chaplain has continued a program of education and consultation through a briefing and letters of welcome given to all new arrivals. He also conducts drilt visits to subordinate units to better avail himself to all personnel who may need his assistance.
- c. Memorial Services are hold for all personnel who lose their lives while in this command. These services are normally conducted by the Eattalien Chaplain, in cases of Roman Catholic personnel, a Catholic Chaplain is also present to say the Requiem Mass. Those services are held in the Division or Brigade Memorial Chapels or in the area of the unit concerned.
- d. Character Guidance: Classes are held each month on the topic prescribed by higher headquarters. The Chaplain conducts these classes for subordinate units whenever requested. In addition, a supplemental orientation shoct is propared by the Chaplain and distributed in sufficient mumbers to the unit training officers for all officers and enlisted non unable to attend class.

#### II. Section 2. Lessons Learned.

#### 1. (U) Personnel:

#### a. Recording of Awards and Decorations.

- (1) OBSERVATION: Recent inspection of our Awards and Decorctions log book revealed that the system we were using was very inefficient and almost impossible to suspense.
- (2) EVALUATION: Under the old system we used one log book for all the companies in the battalion. The log book was divided into three different sections. The first section contained the man's name, unit, award and the date we received the recommondation for the award. The second section contained the same information as the first section except for the date. Here we placed the date it was forwarded to 12th Aviation Group (Combat). The third section contained the same information as the first two with the date again the only exception. Here we placed the date which it was sent back to the individual's unit.
- (3) RECOMMENDATION: That we do away with the three separate sections of the log book. When a recommendation for an award reaches this headquarters, place his rank, name, award, date forwarded to 12th iviation Group (Combat), General Order number and date, and date returned to individual's unit all on the same page.
- (4) COMMAND ACTION: This system has been adopted by the Awards and Decorations Section of this unit and has thus far proved very successful.
- b. Elimination of the Intelligence Officer and Noncommissioned
  Officer from MTOF 1-77G.

- (1) OBSERVATION: The modification to TOE 1-77G excluded the Company Intelligence Officer and Noncommissioned Officer.
- (2) EVALUATION: The assault helicopter company is required to hold a sufficient amount of chasified material to warrant the authorization of qualified personnel to insure proper dissemination and maintenance. The company is required to conduct a vigorous security program on a continuing basis, i.o.., security and intelligence briefings, debriefings, to include censorship and oscape and evasion programs. There are not sufficient numbers of personnel authorized the Operations Section of the company so that required complasis may be placed on the intelligence/security programs; nor are those personnel authorized by present MTOE MOS-qualified to function as intelligence and security personnel.
- (3) RECOMMENDATION: That the duty of Company Intelligence Officer be an additional duty of the Assistant Operations Officer, and that the position of Company Intelligence Noncommissioned Officer be reinstated to the MTOE 1-77G.

#### 2. (U) Operations:

#### a. Combat Demage Due to Mines.

- (1) OBSERVATION: Throo adverteft in the 242nd Aviation Company
  (Assembly Support Holicoptor) have incurred minor demago from detonating minos within the past 60 days.
- (2) EVALUATION: During three separate incidents aircraft received damage from exploding mines while hovering or setting down in a landing zone. One incident was due to a friendly mine which was located to close to the resupply pad and two were due to enemy mines which were detenated.

  Each time, the aircraft had landed were snoke was thrown. In the first incident, the ground personnel failed to notify the aircraft commander of the mine field. During the second two incidents, the personnel in the landing zone failed to clear an area sufficiently large enough to land a CH-47.
- (3) NECOMENDATION: That aviation licison officer stress the importance of properly preparing a lending zone for lending aircraft.
- (4) COMMAND ACTION: Commanders of units in areas normally mixed or booby trapped have been advised that CH-47's will not land until assurance is given that the landing zone has been cloared.

#### b. Presering UH-1 Aircraft for CH-47 Recovery.

- (1) CESERVATION: During two recent recovery missions of UH\_1C gunships belonging to the 187th Aviation Company (Assault Felicopter), the recovered aircraft was found to be too heavy for the CH\_47.
- (2) EVALUATION: The cause of the excessive weight was that the circust was not properly prepared. In one case the UHLIC still has two full rocket pods, both machine guns and ammunition and the crows body armor.

#### (3) RECOMMENDATIONS:

- (e) That pathfinder personnel remove all weapons, ordnance and other loose items from the aircraft.
  - (b) That, if practical, the fuel be drained prior to recovery.
- (c) That pathfinder personnel coordinate by radio with the aircraft commander prior to recovery to insure that loose items, weapons, etc, have been removed.
- (4) COMMAND ACTION: Pathfinder personnel have been briefed on the above requirements.

#### c. Sefety After Autorotation.

- (1) OBSERVATION: Recently a CH-474 experienced an engine fire in flight, and an hazardous incident came about.
- (2) EVALUATION: The fire was extinguished and successful autorotative landing was made. After shut down, the crew chief climbed up the side of the ship to determine the extent of damage, prior to ascertaining that the reter blades had come to a complete stop. As a result, the crew chief was struck in the chest by a rotating blade and knocked from the top of the aircraft, luckily without sustaining any injury except a sore chest.
- (3) RECOMMENDATION: No crewmomber should climb top-side of a rotary wing circreft during emergency or normal shut down while the roter blades are in metion.
- (4) COMMIND ACTION: This unit has started giving an aviation safety class to all rowly assigned crewmembers and they receive a refresher class monthly. This class have been supplemented into the unit training SOP.

#### d. Placement of CH-/7. GH-54 POL Points.

- (1) OBSERVATION: Most helicopter refueling eross in Viotnem have CH\_47, 54 POL points constructed on one end of the refueling line.
- often on the upwind side of the refueling area. This causes the CH-47 to often make an approach passing along side the smaller parked aircraft. The strong roter wash of the CH-47 is often hazardous to smaller aircraft and could be minimized if CH-47 refueling points were constructed at both ends of a refueling area. Regardless of wind direction, an approach could be made and terminated without passing in close proximity to smaller refueling aircraft.
- (3) RECOMMENDATION: That engineer units charged with the construction of refueling areas be advised of this so that in the future, this is taken into consideration.

#### c. Accidental Release of External Cargo.

- (1) OBSERVATION: Recently, an external load was accidentally released by a flight engineer.
- (2) EVALUATION: The reason the accident accured was that the cargo hock release button on the winch hoist control grip was press by mistake when the flight engineer attempted to press the microphone button which is \frac{1}{6} inch below the hook release button on the control grip. This would have been avoided if the control grip was equipped with a protective flip-cover over the earge release button.
- (3) RECOMMENDATION: That the winch/hoist control grip be modified by adding a protective cover guard over the cargo release button.

(4) COMMAND ACTION: This unit will be submitting an Equipment Improvement Recommendation as outlined above.

#### g. Insdequate Aircraft Pre-Flight.

- (1) OBSERVATION: Prior to 1 July 1969, the policy of the 116th Aviation Company (Assault Helicopter) was to let the pilot pre-Flight the aircraft and run it up for a communication and operational check. Due to the inexperience of the pilot a lot of discrepancies were missed.
- (2) EVALUATION: Starting 1 July 1969, a new policy was initiated and made standard for all pre-Flights. The policy is that aircraft commanders will assist the pilots on his pre-Flight and operational check. Since this policy has been in effect we have had a great deal less problems with our flight during the mission because the experience aircraft commander has found many discrepancies the pilots have everlooked and maintenance has been able to correct them before take off time.
- (3) RECOMMENDATION: On all pre-Flights and post flights utilize the experience of the aircraft commander to check the aircraft thoroughly to detect any discrepancies the pilot may over look.
- (4) COMMAND ACTION: This units SOP has been revised to insure Eircraft commanders participate in pro-flights and post flights.

#### g. Artillery Coordination and Combat Assaults.

- (1) OBSERVATION: Some artillery units do not have close coordination between the forward observer and betteres --- resulting in closecalls for helicaptors or short final into a landing zone
  - (2) EVALUATION. Because of distance, bad communication could be

one cause; however, lest minute changes in LZ's length of prep, etc, are frequent causes of an ill-timed prep.

- (3) RECOMMENDATION: That a closer working relationship between arbillery FO's and Air Mission Commanders begin.
- (4) COMMIND ACTION: Air Mission Commanders have been instructed to maintain a close coordination with artiflery liaison officers on the utilization of preps during combat assaults.

#### h. Accidental Discharge of Weapons.

- (1) OBSERVATION: Incidents in the past few months reveal that the bolts of M-60 machine guns on UH-1H models are worn to the extent that when weapons are cleared, a round is still chambered.
- (2) EVALUATION: A worn bolt was the direct cause of an M-60 accidentally discharging a round while being cleared.
- (3) RECOMMENDATION: That all M-60 bolts be inspected carefully to prevent a round from remaining chambered.
- (4) COMMAND ACTION: If bolt still remain a problem, a better method of clearing a weapon will be enforced, i.e., removing the barrel.

#### i. Transition from UH-1C Cunshins to AH-1G (Cobres).

- (1) OBSERVATION: In performing operations combining AH-1G and UH-1C model gunships, we have experienced two problems.
- (2) EVALUATION: The Cobra pilots we were assigned did not have prior experience with assault helicopter company operations. This retarded the officiency of their performance for a period of time. The other problem area was in the maintenance section. We didn't have experienced personnel to

perform the maintenace on the Cobras. This also limited the mission readiness of the aircraft.

(3) RECOMMEND.TION: That before assigning Cobras to another unit that experienced personnel also be assigned, which will definitely make the transition more efficient.

#### j. Air Movement of the Fire Sup ort or Patrol Base.

#### (1) OBSERVATION:

- (a) It has been noted on recent pathfinder operations involving the installation of new fire support or patrol bases, that the air movement of materials for construction, Class V, and artillery pieces can be greatly expedited if:
- 1 Pathfinder support is requested well in advance of the planned movement, and the pathfinder support is requested from the Aviation element supporting the movement.
- 2 Pathfinder team leader for the operation makes coordination with the Infantry unit S-4 rather than the S-3.
- 3 All coordination between the pathfinder and infantry unit, and pathfinder and aviation element is made well in advance of the planned movement.
  - 4 All loads are rigged the day prior to the actual move.

#### (2) EVALUATION:

a. Because the pathfinder detachments oragnic to aviation battalions are familiar with the operation procedures of their battalion, they will consistently be able to provide more valuable support than pathfinders from other units.

- (b) Because the air novement of supplies within the infantry battalion is controlled by the Infantry Battalion S-4, pathfinders working on air movement operations involving supply material should make all coordination with the infantry battalion.
- (c) Because coordination between the aviation element, the infantry unit, and the pathfinders is the key to the success of an air movement operation, as much advance time as possible should be allowed for coordination.
- (d) Because all loads can be picked up in the PZ and delivered to the LZ with a minimum amount of lost blade time while the aircraft waits for loads to be rigged, all loads for an air movement should be rigged and ready to move on the day prior to the actual move.

## (3) RECOMMENDATION:

- (a) Pathfinders support for air movement operations should always be made well in advance of the operation, and the pathfinders should be requested from the axiation unit supporting the operation.
- (b) Pathfinder coordination with the infantry unit for air movement operations should be made with the Infantry Battalion S-4.
- (c) As much time as possible should always be allowed for coordination between the infantry unit, the aviation unit, and the pathfinders in all aimovement operations.
- (d) All leads for an air movement to a new fire support or partrel base location should be rigged a day prior to the actual move.
- (4) COMMAND LOTION: That commanders make maximum utilization of we ming orders with respect to logistical moves. Non organic aviation units should be included in the issuance of warning orders.

# 3. (U) Intelligences

### a. Handling of Secret Meterial.

- (1) OBSERVATION: Companies stationed on the same installation as Battalian Headquarters should not be required to store or maintain secret material.
- (2) EVALUATION: Because of the ready availability of the Bettelion Repository to subordinate companies stationed at the same installation there is no need for the companies to maintain secret material.
- (3) RECOMMENDATION: That all subordinate companies stationed on the same installation as Battalion Herdquarters discontinue maintaining socret materials on a permanent basis.
- (4) COMMAND ACTION: Subordinate compenies stationed on Ou Chi Base Comp along with Battalion Headquarters, no longer maintains secret materials on a permanent basis.

## 4. (U) Logistics:

### a. Rocket Allocations.

- (1) OBSERVATION: It has been noted that 2.75 inch rockets were refused to our units by the 25th Division because we were not supporting the Division on a cortain day.
- (2) EVALUATION: The rocket allocations that we are given for any period are sent directly to Division. Therefore, there was some misunder-standing as to the control of these rockets. They are intended for our gunships in support of any unit, the 25th Division or otherwise, with which we may be working.
- (3) RECOMMENDATION: That the rocket allocations be forwarded to this headquarters rather than to Division so that we may coordinate and regulate our operational use of rockets.
- (4) COMMAND ACTION: A system has been devised whereby the 269th Aviation Battalion (Combat) will directly receive recket allocations from 12th Aviation Group (Combat) Headquarters and then hand carry these allocations to Division G-4 for further coordination. Each of our units will be given a quote as to the number of rockets they may expend in a certain time frame. A small number will be kept in reserve in the event these units have need to exceed their quota.

## b. Motor Maintenance Parts Distribution.

(1) OFSERVITION: It has been noted that there had been a recent trend throughout our units of an increasingly high persontage of deadlined vehicles and generators.

- (2) EVALUATION: Lack of replacement parts for this equipment was apparently the chief cause of the increasing percentile.
- (3) RECOMMENDATION: In order to lower this rising deadline rate, we must first be able to supply our units with necessary materials to repair their equipment. All the needed parts had been placed on requisition but their arrival was not anticipated in the near future. Therefore, the only immediate way to decrease our deadline rate was to swap parts among the comparies within the battalion.
- (4) COMMAND ACTION: Presently, through the 8-4 and particularyly, automotive maintenance section, we are initiating a program whereby we have one unit give (if it is an expendable item) or transfer a part, of which they have an emple number, to a sister unit in the battalion. This has been working quite well and our decreasing deadline rate is a reflection of our progress.

### c. Motor Mointenance M151/1 Jeen.

- (1) OBSERVATION: The M15141 Jeep has a fault in the manufacturing of the universal joint companion flange.
- (2) EVALUATION: The universal joint companion flange is nede in two parts, the flange and a screw in center. When in operation the center backs out or works loose allowing the axle to webble excessively which inturn causes the axle universal joints to fail. It also allows grease to look from the differential which could cause it to fail if neglected for a time.
- (3) RECOMMENDATION: To correct this deficiency remove the flenge from the differential, tighten the center as tight as possible, then braze

it in place. This will keep the center from working loose which will greatly longthen the life of the universal joints and the differential.

(4) COMMIND ACTION: This unit has presently modified one M151L1 joen and the results have been favorable.

#### d. Aircraft Maintenance - Fuel Starvation.

- (1) OBSTRVATION: A UH-1C was experiencing engine failures at flight idle RPM on starting and/or shutdown operation.
- (2) EVALUATION: The engine feilures were traced to fuel starvation. The engine failures occured intermittently at flight idle RPM only. The aircraft could be restarted and flown for a week, day or an hour with no failure or indication of impending failure, and then suddenly quit. Replacement or inspection of the fuel control unit, fuel lines and check valves, electrically operated valves and fuel pumps produced negative results. It was finally found that the main fuel switch was not maintaining proper electrical contact when subjected to certain frequency vibrations at flight idle RPM. The switch was replaced and no further trouble was experienced.
- (3) NECOMMENDATION: Before expending many maintenance man hours of work and down time on the aircraft replacing fuel system components, it is auggested that the main fuel switch be removed and inspected for cleanliness and that proper electrical connection is maintained at all RPM.
- (4) COMMAND ACTION: All main fuel switches were removed and thoroughly inspected and cheaned. All switches were tested by an electrician for proper installation and proper electrical contact during all ranges of RPM.

### 5. (U) Scfety:

- c. Arelysis of Accident Files and Safety Records.
- (1) OBSERVLTION: Limitysis of accident files and safety records indicates that more emphasis on proper emergency procedures is surely needed by the units. Recent analysis indicates that most emergencies encountered in flight result in an unsuccessful landing.
- (2) EVALUATION: Each company safety and standardization officer must monitor and follow up all unit aircraft mishap reports and investigations. Thru enalysis of these investigations at the company level many dangerous trends are discovered. Recent experience indicates knowledge of these trends are the prime tool in any accident prevention program. Unit accident prevention programs must undergo continuous analysis, to keep the program up dated. All accident prevention programs must meet the individual aviator in a workable condition. An accident prevention program which is not workable to the aviator serves no purpose in preventing accidents.
- (3) RECOMMENDATION: That all accident prevention programs undergo continuous analysis, to keep them up dated and workable. All accident prevention programs need to stimulate the aviators interest and intelligence rather than a forced program which tends to simulate adverse reactions with in the aviator.
- (4) COMMAND ACTION: Command emphasis in the field of accident provention is the most vital tool of the program. However, over emphasis and throats of command discipline cause apprehension in the aviators. Maintained supervision with continuous adherence to established directives accountagies and fosters a working accident prevention program. When safety is an attitude

fostered by association with experience and education; accident prevention programs are vital working programs.

### 6. (U) Hecdoverters and Herdoverters Company:

### E. Energoncy Electrical Power Scurces.

- (1) OBSERVATION: Pi&E gonerator supplied electrical power is proving to be erratic and unreliable in some areas.
- (2) EVALUATION: Due to excessive age of generators, near continuous operation, a shortage of repair parts; and in some cases, improperly trained maintenance personnel, PA&E generators may be inoperative for several days. This causes obvious problems with operations of ossential items such as Battalion Operations Center (BOC), dispensary's and mess halls.
- (3) RECOMMEND TION: That all units establish as SOP to cover power outages and maintain operations as near to normal as possible. This SOP should include what organic generators will be hooked up to specific buildings at specific, narked junction box is for oxemple.
- (4) COMMIND ACTION: This unit had the communications section examine our power network and available organic generators, and establish a simple SOP for hesty substitution of organic power for PAME power.

5 Inclosures

Unit Strongth

Oursey of Lossos

4. Alreraft Status

5. Operational Statistics Incls 1 - 3 wd HQ, DA

WILLIAM A. LIWRENCE LTC. FA

Commending

AVBACA-SC (1 Aug 69) 1st Ind SUBJECT: Operational Report-Lessons Learned of the 269th Aviation Battalion (Combat) for the Period 1 May 1969 through 31 July 1969 (U)

DA, HEADQUARTERS 12TH AVIATION GROUP (COMBAT), APO 96266 24 August 1969
TO: Commanding General, II Field Force Vietnam, APO 96266
In accordance with USARV Reg 525-13, subject report is forwarded.
FOR THE COMMANDER:

GORDON M. HUNT Major, Infantry Adjutant AVFRGERE-H (1 Aug 69) 2d Ind SUBJECT: Operational Report-Lessons Learned of the 269th Aviation Battalion (Combat) for the Period 1 May 1969 through 31 July 1969 (U)

DA, HQ II FFORCEV, APO San Francisco 96266 8 SEP 1969

THRU: Commanding General, 1st Aviation Brigade, ATTN: AVBA-C, APO 96307

Commanding General, US Army Vietnam, ATTN: AVHGC(DST), APO 96375

Commander-In-Chief, US Army Pacific, ATTN: GPOP-DT, APO 96558

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D.C. 20310

This headquarters has reviewed and concurs with the Operational Report - Lessons Learned of Headquarters, 269th Aviation Battalion (Combat) for the period ending 31 July 1969.

FOR THE COMMANDER:

G. MACRONALD

ILT, AGC

# CONFIDENTIAL

- AVBAGC-0 (1 Aug 69) 3d Ind SUBJECT: Operational Report - Lessons Learned of the 269th Aviation Battalion (Combat) for the Period 1 May 1969 through 31 July 1969 (U)
- DA, HEADQUARTERS, 1ST AVIATION BRIGADE, APO 96384 18 SEP 1969
- THRU: Commanding General, United States Army Vietnam, ATTN: AVHGC-DST, APO 96375

  Commander-in-Chief, United States Army Pacific, ATTN: GPOP-OT, APO 96558
- To: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D.C. 20310
- 1. (U) This headquarters has reviewed subject report and concurs with the contents as indorsed except as noted below.
- 2. (C) The following additional comments are considered pertinent:
- a. Section I, paragraph 6a, page 17, discusses secure voice radio equipment installation.
- (1) Problems with the wiring in the ZYS modification were experienced. However, in all cases where the unit brought the wiring problems to the attention of the ZYR/ZYS installation team, the wiring problems were corrected.
- (2) The module modification for the AN/ARC-54 is MWO 11-5821-244-30/2. This MWO modifies the transmit audio module for xmode operation. This MWO was published in 1966. Coordination with 34th General Support Group shows all modules passing through the General Support Shops have been modified.
- (3) There has been no evidence in the 1st Aviation Brigade to support the statement that the KYK28 Key Gun goes out of adjustment. The only time this is experienced is when the code setting is not properly seated.
- (4) There is no KYK-28 installation in any Army aircraft. The KYK-28 is a Key Gun. If the intent of this statement was to refer to the KY-28 installation, then it is in error. Neither this headquarters nor the U-ARV Avionics Office is aware of any modification for the control head in this system. The ZYS had an add-on modification which corrected the lack of FM volume control in the initial ZYS modification. This is a modification to the internal wiring of the aircraft and has nothing to do with the control head.
- b. Section II, paragraph 1b, page 22, addresses the requirement for a Company Intelligence Officer and Noncommissioned Officer for the Aviation Company (Assault Helicopter), TOE 1-77G. Neither TOE 1-77G nor MTOE 1-77G, PAC 2/68, provides for a Company Intelligence Officer or

40 CONFIDENTIAL DOWNGRADED AT 3 YEAR INTERVALS; DECLASSIFIED AFTER 12 YEARS. DOD DIR 5200.10

# CONFIBENTIAL

AVBAGC\_0 18 SEP 1969

SUBJECT: Operational Report - Lessons Learned of the 269th Aviation Battalion (Combat) for the Period 1 May 1969 through 31 July 1969 (U)

Noncommissioned Officer. The 269th Aviation Battalion (Combat) has been advised to submit a modification to the MTOE, in accordance with USARV Circular 310-44, dated 31 May 1968, with proper justification for a Noncommissioned Officer with an Intelligence MOS to be added to the Operations Section. Additional MTOE change is required if it is desired that the Assistant Operations Officer be identified by a remark in the MTOE as having the additional duty of Intelligence Officer.

- c. Section II, paragraph 2d, p. e 26, addresses refueling hazards caused by CH-47 and CH-54 refueling points adjacent to those of lighter aircraft. A taxiway should be provided at all refueling areas to permit the ground taxing of CH-54 and CH-47 helicopters without affecting other aircraft refueling. Most refueling area designs are based on existing real estate and user requirements. However, no refueling area design providing an approach directly to the refueling point should be approved since this violates safe operating practices. A letter is being prepared to CG, US Army Engineer Construction Agency Vietnam (USAECAV) recommending future refueling area designs provide an approach pad and an adequate toxiway to the refueling points to permit the safe movement of aircraft in and around the refueling area.
- d. Section II, paragraph 4c(3), pages 33-34, discusses a faulty MblAl jeep universal joint commanion flange. Nonconcur. The removal of the flange from the universal gear is beyond the organization maintenance authorization. The unit has been advised to submit an EIR.
- e. Section II, paragraph 4d, page 34, discusses fuel starvation at flight idle RPM on UH-IC helicopters. A DA Form 2028 will be submitted to Department of the Army recommending a change to TM 55-1520-220-20 trouble shooting section to include the inspection procedure for intermediate fuel starvation problems as stated by the 269th CAB OR-IL. The unit has been advised to submit an EIR.

FOR THE COMMANDER:

Cy of 3d Ind Furn: CO, 269th Avn Bn (Cbt) E. M. GUGAIELMO

41

CONFIDENTIAL

AVHCC-DST (1 Aug 69) 4th Ind SUBJECT: Operational Report-Lessons Learned for the Period Ending 31 July 1969 (UIC: WDUTTO) (RCS CSFOR-65) (R1)

HEADQUARTERS, UNITED STATES ARMY, VIETNAM, APO San Francisco 96375 8 001 198;

TO: Commander in Chief, United States Army, Pacific, ATTN: GPOP-DT, APO 96375

This headquarters has reviewed the Operational Report-Lessons Learned for the quarterly period ending 31 July 1969 from Headquarters, 269th Combat Aviation Battalion and concurs with the report as indorsed.

FOR THE COMMANDER:

C. D. WILSON

Assistant Adjutant General

Cy furn: 269th CAB 1st Avn Bde GPOP-DT (1 Aug 69) 5th Ind SUBJECT: Operational Report of HQ, 269th Aviation Battalion (Combat) for Period Ending 31 July 1969, RCS CSFOR-65 (R1)

HQ, US Army, Pacific, APO San Francisco 96558 18 007 69

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D. C. 20310

This headquarters concurs in subject report as indorsed.

FOR THE COMMANDER IN CHIEF:

C. L. SHORTT

Asst AG

AIRCHAET STATUS
HEADQUARERS 269TH AVIATION BATTALION (COMDLY)
31 July 1969

SUBORDINAIR UNITS	UH_13	13 10/H	UII.	UII_1C	UH-	UH_1D	th th	UH_1H	CH-47	17. 10/H	ditch ditch	0H-6 14th 9/H	tuth tuth	4H-16
HQ 269th ivn Bn (Cbt)	0	0	0	0	0	N	0	0	0	0	m	0	0	0
116th Lvn Co (Aslt Hol)	*	0	*	40	*	17	*	М	0	0	0	0	0	0
187th Avn Co (Aslt Hel)	*	0	*	m	*	0	*	19	0	0	0	0	0	3
242nd 4m Co (Aslt Spt Hol)	٥	0	0	0	0	0	0	0	16	16	2	0	0	0
TOTAL 269th Lvn Bn (Cbt)	0	0	0	₩	0	19	0	8	16	16	10	0	0	М
<i>+</i>														

# 116th Aviation Company (Assault Helicopter) is authorized 31 UH-1 model under MTOE 1-776 dated 28 Oct 68. INCLOSUIG 4 (Vireraft Stetus)

DOWNGRADED AT 3 YEAR INTERVALS; DECLASSIFIED AFTER 12 YEARS. DOD DIR 5200.10

CONFIDENTIAL

Incl 4

CONFIDENTIAL

OPERATIONAL STATISTICS
HEADQUARTERS 269TH AVIATION BATTALION (CONTAIN)
Quertor Ending 31 July 1969

၌		CONI	IDEN	HAL  =
COMBLT ASSAULT DAYS	&	<b>&amp;</b>	0	178
FLYING	8,924	8,827	3,699	76 21,450
A/C DANAGE	19	%	-	97
IOST	-	0	0	1
SAMPANS DAM DEST	5	ત	0	15
SAM	0	0	0	0
STRUCTURES DAM DEST	0	15	0	15
STRUC	0	0	0	0
VC	156	77	0	227
TONS CARGO	18.5	18.7	23,067,0	23,104.2
TROOPS	50,025	43,885	49,333	65,521 143,243
SORTIES	27,390	25,665	12,466	65,521
TIND	116th 4vn Co (4slt Hol)	187th 4vn Co (4s1t Hc1)	2/2nd 1vn Co (Lalt Spt Fel)	TOTAL

INCLOSURE 5 (Operational Statistics)

DOWNGRADED AT 3 YEAR INTERVALS; DECLASSIFIED AFTER 12 YEARS. DOD DIR 5200.10

CONFIDENTIAL

Incl 5

DOCUMENT CONTROL DATA - R & D (Security classification of title, hedy of abstract and indexing annotation must be entered when the everall report in classified)						
I DRIGINATING ACTIVITY (Corporate author)	and the state of t		CURITY CLASSIFICATION			
HQ, OACSFOR, DA, Washington, D.C. 20310			ENTIAL			
, , , , , , , , , , , , , , , , , , , ,		26. GROUP				
3 REPORT TITLE	·	4				
3 REPORT TITLE						
Operational Report - Lessons Learned, HQ, 269th Aviation Battalion						
4. DESCRIPTIVE NOTES (Type of report and Inclusive dates)						
Experiences of unit engaged in counterinsus Author(s) (First name, middle Initial, lest name)	rgency oper	ations, l	May 69 to 31 July 69.			
,						
CO, 269th Aviation Battalion						
. REPURT DATE	76. TOTAL NO. O	FPAGES	7b. NO. OF REFS			
1 August 1969  B. CONTRACTOR GRANT NO.	49					
M. CONTRACT OR GRANT NO.	SA. ORIGINATOR	REPORT NUMB	ER(5)			
b. PROJECT NO	693138					
c. N/A SO OTHER REPORT NOISI (Arry other numbers to			her numbers that may be seeigned			
	this report)					
d.	<u> </u>					
10 DISTRIBUTION STATEMENT						
II. SUPPLEMENTARY NOTES	12. SPONSORING	MILITARY ACTIV	/ITY			
	OACSFOR, D	A, Washing	gton, D.C. 20310			
N/A	L					
11 ABSTRACT						
			·			
			•			
i						
			İ			
	46					
	+0					